



**Settlement at the
Fleet Maintenance Building
Before and After Pictures and Lidar**



**Push Pier and
Polymer
Injection were
used to Stabilize
and Lift the Fleet
Building**




Buckling of Siding Resolved After Lift



Buckling of Siding Due to Settlement

Before



After

Closing of Cracks Caused by the Settlement



Before



After

Before Staircase and Door Landing Replaced

Before




After




Lift Confirmed through Survey and Lidar

Before



Majority of settlement found at west entry door

After



Building Lifted as per Survey and confirmed by Lidar