

Attachment E - Existing Conditions



Picture 1
No Infrastructure



Picture 2
No Infrastructure



Picture 3
Flood Prone Area



Picture 4
Not ADA compliant – Lack of Signage

Attachment E - Existing Conditions



Picture 5
Trail Adjacent to Roadway



Picture 6
No Existing Ped Crossing



Picture 7
Abandoned rail - user hazard



Picture 8
Trail adjacent to Roadway at Grade


Attachment E - Existing Conditions



Picture 9
Flood Prone Area



Picture 10
Trail Adjacent to Roadway at Grade



Picture 11
Lack of Buffer between Traffic



Picture 12
No Lighting Lack of Amenities

Attachment E - Existing Conditions



Picture 13
No Shade



Picture 14
No Shade



Picture 15
Flood Prone Area, No traffic barrier, No Shade



Picture 16
Future Connection

Attachment E - Existing Conditions



Picture 17
No Trash Receptacles



Picture 18
Lack of Access to Adjacent Apartments



Picture 19
Lack of amenities



Picture 20
Not ADA compliant, Lack of Safety Signage

Attachment E - Existing Conditions




Picture 21
Not ADA compliant Lack of Signage



Picture 22
Lack of Separation from Rail



Picture 23
Not ADA Compliant Exposed Crossing



Picture 24
Safety Concern - Cyclists in Roadway

Attachment E - Existing Conditions



Picture 25
Safety Concern - Cyclists in Roadway