

Pic.1 - Retaining wall in comparison to the adjacent brick showing the tilt in the wall. The yellow arrows show the visible brick at the top vs. the bottom. The leaning of the wall has caused more coverage of the brick at the top of the wall.





Pic 2. Example of cracking in the wall - The red arrows follow the crack down the wall





Pic. 3/4 - Gap Between upper Concrete Pad/Deck and the Retaining wall

